DAILY WORK ORDER	
	Work Period:
Bossert Manufacturing	8/06/87
Contractor: O. H. Materials Contractor Rep.: Paul Street	OSC: Jack D. Harmon
WORK PLANNED/AUTHORIZED:  1.) Continue to clean out sumps (Sumps #22, #23, and #24)  2.) Continue to laser first floor of area #11 and sumps #59, #60 & #61  3.) Collect samples of area #13, first floor and areas #14 and #15, pending wetness of surfaces, to verify effectiveness of decontamination.  4.) If dry, scrape sludge off pool in water treatment system.  5.) Clean out V.R. using skid unit and Level B protection.  6.) Stage acid containers in area #5 for disposal.	Yes No Continues  1.) (x) ( ) ( )  2.) (x) ( ) ( )  3.) ( ) ( ) (x)  4.) (x) ( ) ( )
(1) Decon trailer (3) Bobcats (1) Command Post Trailer	EQUIPMENT USED FROM PREVIOUS DAY:  All Authorized COMMENTS:
(1) Response Manager (2) Laborer (1) Lab Technician (2)	(1) Foreman (3) (2) Foreman (2) (1) Field Clerk (4) Clean-up Technician (2) (1) Operator (2)
Contractor Signature:	OSC Signature:
Date: 6/8/7	1 ate: 8 6 87